

- 1) Make a 3D rendering of this part, including dimensions. For extra credit, use trueSpace to make a rendering of flying through it to show the threads.
- 2) Machine it out of aluminum.
- 3) For extra credit, model and animate its fundamental mode in ANSYS and find the resonant frequency.

